



In case of doubt on the porosity of the support, test the water drop by pouring a few drops of water on the support.

If the drop of water is absorbed in less than 10 seconds, the support is said to be porous. Beyond this, the support is closed.



Depending on the type of surface, apply the Prim or Prim plus either with a 250 mm roll or with a 500 mm roll.  
Let dry from 30 minutes to 2 hours depending on temperature.  
Clean tools with water.

On a closed surface, apply the Prim or Prim plus either with a 250 mm roll or with a 500 mm roll.  
Let dry from 30 minutes to 2 hours depending on temperature.  
Clean tools with water.